




Exercise 3-16



Exercise 3-17







Exercise 3-18



Exercise 3-19

Make a welded assembly out of parts 3-16 through 3-18 as shown in the drawing on the right. Apply the welds as shown in the assembly drawing.



Exercise 3-20	
Exercise 3-21	

Exercise 3-22

Make an assembly out of parts 3-19 through 3-21. Use a hex head screw (ISO 4014) M12x65 and a hex nut (ISO 4034) to secure the pin.

