Al-Mustaqbal University
College of Science
Department of Medical Physics
The Fourth Stage




# Radiation Protection

## LECTURE EIGHT

X Rays, X-Ray Regulations, Basic Nuclear Physics

Prof. Dr Anees Ali Al-Jubouri

2024-2025



#### LECTURE EIGHT: X- Rays and Basic Nuclear Physics

- \* X-Ray
- **❖** Properties of X-Ray
- **❖** Production of X-Ray
  - Bremsstrahlung "braking radiation "
  - Characteristic X-ray

## **❖** X-Ray Regulations

☐ X-rays are a form of electromagnetic radiation that has a higher energy and can pass through most objects, including the body

#### **☐** Properties of X-Ray

- X-ray is a type of electromagnetic radiation with frequency of 10<sup>18</sup> Hz and wavelength of 10<sup>-10</sup> m (high frequency and very short wavelength).
- X-ray has the ability to pass through liquids, solids, gases and many materials.
- X-ray is traveling in a straight line.
- X-ray is invisible to the eye.
- Long x-ray exposure can be harmful to living organisms, and short exposure to x-rays is not harmful.
- X-rays can be a very dangerous type of radiation because they have a high frequency and high energy.
- When x-rays hit the material, electrons of this material will be ejected from the atom leaving behind a positive charge. For this reason, x-ray radiation is sometimes known as ionizing radiation.

#### **☐** Production of X-Ray Beams

There are various atomic processes that can produce X-ray photons, and they all occur in the heavy atoms of tungsten.

## **One**: Bremsstrahlung "braking radiation."

#### **Two:** Characteristic X-ray.

They can both occur in the heavy atoms of tungsten. X-rays are photons of electromagnetic radiation produced when a target of heavy metal (Tungsten is often the material chosen for the target or anode of the x-ray tube) is struck by electrons traveling at high speed. It is difficult to accelerate the electrons in air, so the process has to be curried in vacuum. Only about 1 % of the electrons produce an X-ray photon; the rest is lost in heating up the target.

## One: Bremsstrahlung "braking radiation."

Braking radiation is produced when a high-speed electron interacts with a nucleus, as follows:




Diagram showing the generation process of X-ray (braking radiation)

- When the electron passes close to the nucleus, it will be deviated from its original path due to Coulomb forces (Maxwell's theory)
- ➤ So, according to Maxwell's general theory of electromagnetic rays, the energy increase through a vacuum by the electromagnetic field.
- As the electron approaches the nucleus, it will be affected by the electromagnetic field emanating from the nucleus, and it will suffer a sudden negative acceleration and deviation as a result of this.
- Thus, the deviation of the electron from its path causes lose its energy in the form of Bremsstrahlung x-ray.

# <u>Two</u>: Characteristic X-ray




Diagram showing the generation process of X-ray (Characteristic X-ray)

### LECTURE EIGHT: X-Rays, X-Ray Regulations, Basic Nuclear Physics

Characteristic X-rays are produced when an electron incident on the atom, as follows:

- The incident electron (which carries a kinetic energy) on the atom causes the electron to move out of the K, L, or M orbitals, leaving the atom ionized.
- This electron will carry an energy that is its binding energy in its orbit from which it exited.
- After the short lifetime of the excited electrons, they return to the lower energy state or ground state (spontaneous) by releasing energy in the form of photons.
- This photons (releasing energy) represents X-ray.

#### **□** X-Ray Regulations

The regulations on the handling of X rays are very similar to the regulations on standard radiation protection. The X-ray regulations in the European Union apply to those X-ray tubes and X-ray installations in which electrons are accelerated at least to 5 keV and in which they are limited to a maximum energy of 1 MeV. All installations in which electrons can be accelerated to energies beyond 1MeV are subject to the regulations of standard radiation protection.

Devices and installations that produce unwanted radiation, like old-fashioned TV screens, where electrons are accelerated up to energies of something like 20 keV, do not require a license if a dose rate of 1  $\mu$ Sv/h at a distance of 10 cm from the surface is not exceeded or if they are approved by the competent authority by way of a design approval.

## LECTURE EIGHT: X=Rays, X-Ray Regulations, Basic Nuclear Physics

The X-ray regulations, of course, mainly concern X-ray tubes used for X-ray diagnosis and X-ray therapy on humans. It is desirable to obtain the best X-ray image available for a particular radiation exposure. At the same time one should try to reduce the radiation exposure by improving the X-ray detection system and image reconstruction without affecting the image quality. The radiation dose of the patient has to be documented. If the Rest. Prof. Dr. Forat Hamilan | Department of Miles |

Asst. Prof. Dr. Forat Hamilan | Department of Miles |

Asst. Prof. Dr. Forat Hamilan |

Asst. Prof. Dr. Forat patient wants a copy for patients of the documentation about the received X-ray doses, it has to be provided to the patient.